




Pole	Ngarkesa	Kodi	Çmimi
1	16 A -PSK11	PSA016AK141E	
1	20 A -PSK11	PSA020AK141E	
1	25 A -PSK11	PSA025AK141E	
1	32 A -PSK21	PSA032AK141E	
1	40 A -PSK21	PSA040AK141E	
1	50 A -PSK31	PSA050AK141E	
1	63 A -PSK31	PSA063AK141E	
1	80 A	PSA080AK141E	




Pole	Ngarkesa	Kodi	Çmimi
2	16 A -PSK11	PSA016AK241E	
2	20 A -PSK11	PSA020AK241E	
2	25 A -PSK11	PSA025AK241E	
2	32 A -PSK21	PSA032AK241E	
2	40 A -PSK21	PSA040AK241E	
2	50 A -PSK31	PSA050AK241E	
2	63 A -PSK31	PSA063AK241E	
2	80 A	PSA080AK241E	




Pole	Ngarkesa	Kodi	Çmimi
3	16 A -PSK11	PSA016AK341E	
3	20 A -PSK11	PSA020AK341E	
3	25 A -PSK11	PSA025AK341E	
3	32 A -PSK21	PSA032AK341E	
3	40 A -PSK21	PSA040AK341E	
3	50 A -PSK31	PSA050AK341E	
3	63 A -PSK31	PSA063AK341E	
3	80 A	PSA080AK341E	



Pole	Ngarkesa	Kodi	Çmimi
3+Neutër	16 A -PSK11	PSA016AK941E	
3+Neutër	20 A -PSK11	PSA020AK941E	
3+Neutër	25 A -PSK11	PSA025AK941E	
3+Neutër	32 A -PSK21	PSA032AK941E	
3+Neutër	40 A -PSK21	PSA040AK941E	
3+Neutër	50 A -PSK31	PSA050AK941E	
3+Neutër	63 A -PSK31	PSA063AK941E	
3+Neutër	80 A	PSA080AK941E	




Pole	Ngarkesa	Kodi	Çmimi
4	16 A -PSK11	PSA016AK441E	
4	20 A -PSK11	PSA020AK441E	
4	25 A -PSK11	PSA025AK441E	
4	32 A -PSK21	PSA032AK441E	
4	40 A -PSK21	PSA040AK441E	
4	50 A -PSK31	PSA050AK441E	
4	63 A -PSK31	PSA063AK441E	
4	80 A	PSA080AK441E	





Pole	Ngarkesa	Kodi	Çmimi
5	16 A -PSK12	PSA016AK541E	
5	20 A -PSK12	PSA020AK541E	
5	25 A -PSK12	PSA025AK541E	
5	32 A -PSK22	PSA032AK541E	
5	40 A -PSK22	PSA040AK541E	
5	50 A	PSA050AK541E	
5	63 A	PSA063AK541E	
5	80 A	PSA080AK541E	



Pole	Ngarkesa	Kodi	Çmimi
1	16 A -PSK11	PSA016AK131S	
1	20 A -PSK11	PSA020AK131S	
1	25 A -PSK11	PSA025AK131S	
1	32 A -PSK21	PSA032AK131S	
1	40 A -PSK21	PSA040AK131S	
1	50 A -PSK31	PSA050AK131S	
1	63 A -PSK31	PSA063AK131S	
1	80 A	PSA080AK131S	





Pole	Ngarkesa	Kodi	Çmimi
2	16 A -PSK11	PSA016AK231S	
2	20 A -PSK11	PSA020AK231S	
2	25 A -PSK11	PSA025AK231S	
2	32 A -PSK21	PSA032AK231S	
2	40 A -PSK21	PSA040AK231S	
2	50 A -PSK31	PSA050AK231S	
2	63 A -PSK31	PSA063AK231S	
2	80 A	PSA080AK231S	





Pole	Ngarkesa	Kodi	Çmimi
3	16 A -PSK11	PSA016AK331S	
3	20 A -PSK11	PSA020AK331S	
3	25 A -PSK11	PSA025AK331S	
3	32 A -PSK21	PSA032AK331S	
3	40 A -PSK21	PSA040AK331S	
3	50 A -PSK31	PSA050AK331S	
3	63 A -PSK31	PSA063AK331S	
3	80 A	PSA080AK331S	





Pole	Ngarkesa	Kodi	Çmimi
3+Neutër	16 A -PSK11	PSA016AK831S	
3+Neutër	20 A -PSK11	PSA020AK831S	
3+Neutër	25 A -PSK11	PSA025AK831S	
3+Neutër	32 A -PSK21	PSA032AK831S	
3+Neutër	40 A -PSK21	PSA040AK831S	
3+Neutër	50 A -PSK31	PSA050AK831S	
3+Neutër	63 A -PSK31	PSA063AK831S	
3+Neutër	80 A	PSA080AK831S	




Pole	Ngarkesa	Kodi	Çmimi
4	16 A -PSK11	PSA016AK431S	
4	20 A -PSK11	PSA020AK431S	
4	25 A -PSK11	PSA025AK431S	
4	32 A -PSK21	PSA032AK431S	
4	40 A -PSK21	PSA040AK431S	
4	50 A -PSK31	PSA050AK431S	
4	63 A -PSK31	PSA063AK431S	
4	80 A	PSA080AK431S	




Pole	Ngarkesa	Kodi	Çmimi
5	16 A -PSK12	PSA016AK531S	
5	20 A -PSK12	PSA020AK531S	
5	25 A -PSK12	PSA025AK531S	
5	32 A -PSK22	PSA032AK531S	
5	40 A -PSK22	PSA040AK531S	
5	50 A	PSA050AK531S	
5	63 A	PSA063AK531S	
5	80 A	PSA080AK531S	







Pole	Ngarkesa	Kodi	Çmimi
1	16 A -PSK11	PSA016KD133S	
1	20 A -PSK11	PSA020KD133S	
1	25 A -PSK11	PSA025KD133S	
1	32 A -PSK21	PSA032KD133S	
1	40 A -PSK21	PSA040KD133S	
1	50 A -PSK31	PSA050KD133S	
1	63 A -PSK31	PSA063KD133S	
1	80 A	PSA080KD133S	




Pole	Ngarkesa	Kodi	Çmimi
2	16 A -PSK11	PSA016KD233S	
2	20 A -PSK11	PSA020KD233S	
2	25 A -PSK11	PSA025KD233S	
2	32 A -PSK31	PSA032KD233S	
2	40 A -PSK31	PSA040KD233S	
2	50 A	PSA050KD233S	
2	63 A	PSA063KD233S	
2	80 A	PSA080KD233S	




Pole	Ngarkesa	Kodi	Çmimi
3	16 A -PSK12	PSA016KD333S	
3	20 A -PSK12	PSA020KD333S	
3	25 A -PSK12	PSA025KD333S	
3	32 A -PSK31	PSA032KD333S	
3	40 A -PSK31	PSA040KD333S	
3	50 A	PSA050KD333S	
3	63 A	PSA063KD333S	
3	80 A	PSA080KD333S	



Pole	Ngarkesa	Kodi	Çmimi
2	16 A -PSK11	PSA016KD234S	
2	20 A -PSK11	PSA020KD234S	
2	25 A -PSK11	PSA025KD234S	
2	32 A -PSK21	PSA032KD234S	
2	40 A -PSK21	PSA040KD234S	
2	50 A -PSK31	PSA050KD234S	
2	63 A -PSK31	PSA063KD234S	
2	80 A	PSA080KD234S	





Pole	Ngarkesa	Kodi	Çmimi
3	16 A -PSK12	PSA016KD334S	
3	20 A -PSK12	PSA020KD334S	
3	25 A -PSK12	PSA025KD334S	
3	32 A -PSK22	PSA032KD334S	
3	40 A -PSK22	PSA040KD334S	
3	50 A	PSA050KD334S	
3	63 A	PSA063KD334S	
3	80 A	PSA080KD334S	





Pole	Ngarkesa	Kodi	Çmimi
4	16 A -PSK12	PSA016KD434S	
4	20 A -PSK12	PSA020KD434S	
4	25 A -PSK12	PSA025KD434S	
4	32 A -PSK22	PSA032KD434S	
4	40 A -PSK22	PSA040KD434S	
4	50 A	PSA050KD434S	
4	63 A	PSA063KD434S	
4	80 A	PSA080KD434S	



Pole	Ngarkesa	Kodi	Çmimi
0-1-2	16 A -PSK11	PSA016KSI32S	
0-1-2	20 A -PSK11	PSA020KSI32S	
0-1-2	25 A -PSK11	PSA025KSI32S	
0-1-2	32 A -PSK21	PSA032KSI32S	
0-1-2	40 A -PSK21	PSA040KSI32S	
0-1-2	50 A -PSK31	PSA050KSI32S	
0-1-2	63 A -PSK31	PSA063KSI32S	
0-1-2	80 A	PSA080KSI32S	





Pole	Ngarkesa	Kodi	Çmimi
0-3	16 A -PSK11	PSA016KSI33S	
0-3	20 A -PSK11	PSA020KSI33S	
0-3	25 A -PSK11	PSA025KSI33S	
0-3	32 A -PSK21	PSA032KSI33S	
0-3	40 A -PSK21	PSA040KSI33S	
0-3	50 A -PSK31	PSA040KSI33S	
0-3	63 A -PSK32	PSA063KSI33S	
0-3	80 A	PSA080KSI33S	





Pole	Ngarkesa	Kodi	Çmimi
0-4	16 A -PSK12	PSA016KSI34S	
0-4	20 A -PSK12	PSA020KSI34S	
0-4	25 A -PSK12	PSA025KSI34S	
0-4	32 A -PSK22	PSA032KSI34S	
0-4	40 A -PSK22	PSA040KSI34S	
0-4	50 A -PSK32	PSA050KSI34S	
0-4	63 A -PSK32	PSA063KSI34S	
0-4	80 A	PSA080KSI34S	





Pole	Ngarkesa	Kodi	Çmimi
0-5	16 A -PSK12	PSA016KSI35S	
0-5	20 A -PSK12	PSA020KSI35S	
0-5	25 A -PSK12	PSA025KSI35S	
0-5	32 A -PSK22	PSA032KSI35S	
0-5	40 A -PSK22	PSA040KSI35S	
0-5	50 A	PSA063KSI35S	
0-5	63 A	PSA080KSI35S	
0-5	80 A	PSA080KSI35S	





Pole	Ngarkesa	Kodi	Çmimi
0-6	16 A -PSK12	PSA016KSI26S	
0-6	20 A -PSK12	PSA020KSI26S	
0-6	25 A -PSK12	PSA025KSI26S	
0-6	32 A -PSK22	PSA032KSI26S	
0-6	40 A -PSK22	PSA040KSI26S	
0-6	50 A	PSA050KSI26S	
0-6	63 A	PSA063KSI26S	
0-6	80 A	PSA080KSI26S	





Pole	Ngarkesa	Kodi	Çmimi
0-7	16 A -PSK12	PSA016KSI27S	
0-7	20 A -PSK12	PSA020KSI27S	
0-7	25 A -PSK12	PSA025KSI27S	
0-7	32 A -PSK22	PSA032KSI27S	
0-7	40 A -PSK22	PSA040KSI27S	
0-7	50 A	PSA063KSI27S	
0-7	63 A	PSA080KSI27S	
0-7	80 A	PSA080KSI34S	





**Çelës trefazor për dy shpejtësi 0-1-2**




Pole	Ngarkesa	Kodi	Çmimi
3 fazore	16 A -PSK12	PSA016CD332S	
	20 A -PSK12	PSA020CD332S	
	25A -PSK12	PSA025CD332S	
	32A-PSK22	PSA032CD332S	
	40A-PSK22	PSA040CD332S	
	50A	PSA050CD332S	
	63A	PSA063CD332S	
	80A	PSA080CD332S	

**Çelës trefazor për dy shpejtësi 1-0-2**





Pole	Ngarkesa	Kodi	Çmimi
3 fazore	16 A -PSK12	PSA016CD334S	
	20 A -PSK12	PSA020CD334S	
	25A -PSK12	PSA025CD334S	
	32A-PSK22	PSA032CD334S	
	40A-PSK22	PSA040CD334S	
	50A	PSA050CD334S	
	63A	PSA063CD334S	
	80A	PSA080CD334S	

**Çelës trefazor yll-trekëndësh**


Pole	Ngarkesa	Kodi	Çmimi
3-fazorë	16 A -PSK12	PSA016MS335S	
	20 A -PSK12	PSA020MS335S	
	25 A -PSK12	PSA025MS335S	
	32 A -PSK22	PSA032MS335S	
	40 A -PSK22	PSA040MS335S	
	50 A	PSA050MS335S	
	63 A	PSA063MS335S	
	80 A	PSA080MS335S	

**Çelës trefazor ndërrim sensi majtas-djathtas 1-0-2**


Pole	Ngarkesa	Kodi	Çmimi
3 fazore	16 A -PSK12	PSA016MS334S	
	20 A -PSK12	PSA020MS334S	
	25A -PSK12	PSA025MS334S	
	32A-PSK22	PSA032MS334S	
	40A-PSK22	PSA040MS334S	
	50A-PSK32	PSA050MS334S	
	63A-PSK32	PSA063MS334S	
	80A	PSA080MS334S	

**Çelës trefazor ndërrim sensi majtas-djathtas (2)-0-1 pozicioni 2 me rikthim**


Pole	Ngarkesa	Kodi	Çmimi
3-fazorë	16 A -PSK12	PSA016MS336S	
	20 A -PSK12	PSA020MS336S	
	25 A -PSK12	PSA025MS336S	
	32 A -PSK22	PSA032MS336S	
	40 A -PSK22	PSA040MS336S	
	50 A	PSA050MS336S	
	63 A	PSA063MS336S	
	80 A	PSA080MS336S	

Pole	Ngarkesa	Kodi	Çmimi	Voltmeter	Diagram	Image
3 fazore	10 A -PSK11	PSA010OK421S				
	16 A -PSK11	PSA016OK421S				
	20 A -PSK11	PSA020OK421S				
3 fazore	10 A -PSK11	PSA010OK422S				
	16 A -PSK11	PSA016OK422S				
	20 A -PSK11	PSA020OK422S				
3 fazore	10 A -PSK12	PSA010OK426S				
	16 A -PSK12	PSA016OK426S				
	20 A -PSK12	PSA020OK426S				
3 fazore	10 A -PSK12	PSA010OK723S				
	16 A -PSK12	PSA016OK723S				
	20 A -PSK12	PSA020OK723S				

Kodi	Dimensionet	Mbrojtja	Çmim	Kodi	Dimensionet	Mbrojtja	Çmim
PSK11	75x85x65 (mm)	IP54		PSK11E	75x85x65 (mm)	IP65	
PSK21	75x85x90 (mm)	IP54		PSK21E	75x85x90 (mm)	IP65	
PSK31	91x100x73 (mm)	IP54		PSK31E	91x100x73 (mm)	IP65	
PSK12	91x100x103 (mm)	IP54		PSK12E	91x100x103 (mm)	IP65	
PSK22	106x116x86 (mm)	IP54		PSK22E	106x116x86 (mm)	IP65	
PSK32	106x116x128 (mm)	IP54		PSK32E	106x116x128 (mm)	IP65	



PSK11



PSK12



PSK21



PSK22




PSK31




PSK32




Pole	Ngarkesa	Kodi	Çmimi
1P	16A	YCBZ-401P16	
	25A	YCBZ-401P25	
	32A	YCBZ-401P32	
	40A	YCBZ-401P40	




Pole	Ngarkesa	Kodi	Çmimi
2P	16A	YCBZ-402P16	
	25A	YCBZ-402P25	
	32A	YCBZ-402P32	
	40A	YCBZ-402P40	



Pole	Ngarkesa	Kodi	Çmimi
3P	16A	YCBZ-403P16	
	25A	YCBZ-403P25	
	32A	YCBZ-403P32	
	40A	YCBZ-403P40	



Pole	Ngarkesa	Kodi	Çmimi
4P	16A	YCBZ-404P16	
	25A	YCBZ-404P25	
	32A	YCBZ-404P32	
	40A	YCBZ-404P40	



Pole	Ngarkesa	Kodi	Çmimi
4 P	63A	YCBZ125/4063	
	80A	YCBZ125/4080	
	100A	YCBZ125/4100	

